


hole pattern for
Porter Cable 1001
3 x drill and c-sink
for 10-24 machine screw

4 x #10 dill



2 x 1/4 drill

Ø0.750

print full size on 11x17 paper
and use as template